



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**17346-73-3347**  
State Number  
**24169**

#### EQUIPMENT INSPECTED

State Number: <b>24169</b>	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2500	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 3	Installed: 09/20/2006	Rope Size: 0
Volts: 208	Complied: 09/20/2006	Entrances: 1
OWNER	OCCUPANT	
SNR 27 CEDAR RIDGE OWNER LLC	CEDAR RIDGE RETIREMENT CENTER	
5885 MEADOWS RD STE 500	2680 MEBANE STREET	
LAKE OSWEGO, OR, 97035	BURLINGTON, NC, 27215	

#### INSPECTION INFORMATION

Inspection Date 12/12/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

#### VIOLATIONS

2.15.2.2	Clean & lubricate the car guiding means
2.14.7.1.2	Place the passenger cab interior lights in working order. 50 lx or 5 fc @ the cab floor.
8.6.4.13.1(i)	Place the door restrictor in proper working order.
8.6.4.7	Clean the pit and the pit equipment.
8.6	Place in case of fire sign at each landing

Items must be corrected by: 02/10/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Evette Maynard 336 229 2002

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

SNR 27 CEDAR RIDGE OWNER LLC  
5885 MEADOWS RD STE 500  
LAKE OSWEGO, OR, 97035