

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17347-70-5870 State Number 1317

76

	EQUIPMENT INSPECTED		
Type of Unit: Passenger  Manuf: MONARCH  Installed: 08/25/1966		Floor to Floor: 1 to 3 Speed: 100 Rope Size: 1/2 Entrances: 1	
Compiled: 06/2	OCCUPANT		
	227 SUNSET AVE ASHEBORO, NC, 27203		
п	NSPECTION INFORMATION		
Type Inspection Condemned	Certificate Status Not Issued	Inspector 70 - Darnley	County RANDOLPH
	VIOLATIONS		
ting on Corrected Violations Forn	n when the following corrections	have been made in order to b	ring your equipment into
	Manuf: MONA Installed: 08/25 Complied: 08/2	Type of Unit: Passenger Manuf: MONARCH Installed: 08/25/1966 Complied: 08/25/1966  OCCUPANT POWERHOUSE 227 SUNSET AV ASHEBORO, NO  INSPECTION INFORMATION  Type Inspection Condemned Certificate Status Not Issued	Type of Unit: Passenger  Manuf: MONARCH Installed: 08/25/1966 Complied: 08/25/1966  OCCUPANT POWERHOUSE GYM 227 SUNSET AVE ASHEBORO, NC, 27203  INSPECTION INFORMATION  Type Inspection Condemned Certificate Status Not Issued Floor to Floor: 1 Speed: 100 Rope Size: 1/2 Entrances: 1  OCCUPANT POWERHOUSE GYM 227 SUNSET AVE ASHEBORO, NC, 27203

P O BOX 1104 ASHEBORO, NC, 27203

JEFFERY SCHWARZ