



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17354-48-2473
State Number
25774

EQUIPMENT INSPECTED

State Number: **25774** Type of Unit: Passenger Floor to Floor: 1 to 3
Capacity: 2500 Manuf: SCHINDLER Speed: 100
Landings: 3 Installed: 04/28/2009 Rope Size:
Volts: 208 Complied: 04/28/2009 Entrances: 1

OWNER

PALMS AT LONG BAY - 2000
1240 EAGLECREST DRIVE
STANLEY, NC, 28164

OCCUPANT

THE PALMS @ LONG BAY
120 SE 58TH ST
OAK ISLAND, NC, 28465

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
12/20/2017	Routine	Re-issued	48 - Martin	BRUNSWICK

10

VIOLATIONS

8.6.4.7 Clean the pit and the pit equipment.

Items must be corrected by: 01/19/2018

Elevator Name: #1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

PALMS AT LONG BAY - 2000
1240 EAGLECREST DRIVE
STANLEY, NC, 28164