



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17354-75-559
State Number
26812

EQUIPMENT INSPECTED

State Number: 26812	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: SCHINDLER	Speed: 100
Landings: 2	Installed: 06/09/2009	Rope Size:
Volts: 208	Complied: 06/09/2009	Entrances: 1
OWNER	OCCUPANT	
ARDEN SEVENTH DAY ADVENTIST CHURCH	ARDEN SEVENTH DAY ADVENTIST CHURCH	
35 AIRPORT ROAD	35 AIRPORT ROAD	
ARDEN, NC, 28704	ARDEN, NC, 28704	

INSPECTION INFORMATION

Inspection Date 12/20/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 75 - Edwards	County BUNCOMBE	11 A
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------	------

VIOLATIONS

- 2.14.7.1.4 Place the car top lights in working order. 100 lx or (10 fc) measured at the point of any elevator part or equipment, where maintenance or inspection is to be performed from the car top.
- 8.6.1.4.1(a) Properly document maintenance records.
- 8.6.1.4.1 Provide an updated Firefighters Emergency Operation log. (Monthly)
- 8.6.5.14.1 Provide the annual relief valve and hydraulic system pressure test.

Items must be corrected by: 02/18/2018

Elevator Name: 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Finley Wetmore 828-684-6780

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ARDEN SEVENTH DAY ADVENTIST CHURCH
35 AIRPORT ROAD
ARDEN, NC, 28704