

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17355-73-2874 State Number 24228

	I	EQUIPMENT INSPECTED		
State Number: 24228 Capacity: 2000	Type of Unit: Passenger  Manuf: OTIS		Floor to Floor: 1 to 3 Speed: 125	
Landings: 3 Volts: 208	Installed: 10/31 Complied: 10/3		Rope Size: 0 Entrances: 1	
OWNER	Compiled: 10/3	OCCUPANT	Littranees. 1	
ELON UNIVERSITY		OAKS BUILDING (B)		
803 HAGGARD AVENUE		1002 ELON ACORN DI	RIVE	
ELON, NC, 27244		ELON, NC, 27244		
	IN	SPECTION INFORMATION		
Inspection Date 12/21/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
		VIOLATIONS		
Elevator Name: BUILDING (B Notify the Elevator Bureau in writin complainace with current codes. Violations pointed out to: Jeremy E	g on Corrected Violations Form	when the following corrections have	e been made in order to br Inspector	ing your equipment into

ELON UNIVERSITY

ELON, NC, 27244

803 HAGGARD AVENUE