



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**17355-73-4558**  
State Number  
**24196**

EQUIPMENT INSPECTED

State Number: <b>24196</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: OTIS	Speed: 125
Landings: 2	Installed: 03/07/2007	Rope Size: 0
Volts: 208	Complied: 03/07/2007	Entrances: 1
OWNER	OCCUPANT	
OAKS BUILDING (F)	OAKS BUILDING	
416 N WILLIAMSON AVE	416 N WILLIAMSON AVENUE	
ELON, NC, 27244	ELON, NC, 27244	

INSPECTION INFORMATION

Inspection Date 12/21/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

2.2.5.1 Place the pit lights in working order. 100 lx or 10 fc @ the pit floor.

Items must be corrected by: 02/19/2018

Elevator Name: (CampusPolice/Security)

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Jeremy elon 336 380 6126

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

OAKS BUILDING (F)  
416 N WILLIAMSON AVE  
ELON, NC, 27244