

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18002-48-5731 State Number 23562

		EQUIPMENT INSPECTED			
State Number: 23562 Type of Unit: Pass		senger Floor to Floor: 1 to 2		por: 1 to 2	
Capacity: 2100	Manuf: THYSSE		Speed: 95 Rope Size: 0 Entrances: 1		
Landings: 2	Installed: 05/24/2	2006			
Volts: 208	Complied: 10/12				
OWNER		OCCUPANT	OCCUPANT		
COLDWELL BANKER COMM	ERCIAL SUNCOAST		BLDG SEA COAST ADV	ANTAGE	
PROPERTY MANAGEMENT DIVISION			4911 LONGBEACH ROAD		
WILMINGTON, NC, 28403		SOUTH PORT, NC, 28461			
	IV	NSPECTION INFORMATION			
Inspection Date 01/02/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
Elevator Name: #1					
Notify the Elevator Bureau in writi	ng on Corrected Violations Form	when the following corrections	have been made in order to	bring your equipment into	
complainace with current codes.			Υ .		
Violations pointed out to: VICKI		Inspector			
1	Γo make changes to the invoice n	nailing address please call: 919-7	33-0372		
THIS IS NOT AN	COLDWELL BANKER COMMERCIAL SUNCOAST				

PROPERTY MANAGEMENT DIVISION

WILMINGTON, NC, 28403