



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18003-73-3838
State Number
30448

EQUIPMENT INSPECTED

| | | |
|----------------------------|---|------------------------|
| State Number: 30448 | Type of Unit: Passenger | Floor to Floor: 1 to 3 |
| Capacity: 2100 | Manuf: TKE | Speed: 150 |
| Landings: 3 | Installed: 09/14/2016 | Rope Size: |
| Volts: 460 | Complied: | Entrances: 1 |
| OWNER | OCCUPANT | |
| ELON UNIVERSITY | ELON UNIVERSITY COMMUNICATIONS/PAVILION | |
| CAMPUS BPX 84823 | 129 N WILLIAMSON AVENUE | |
| ELON, NC, 27244 | BURLINGTON, NC, 27244 | |

INSPECTION INFORMATION

| | | | | |
|-------------------------------|----------------------------|---------------------------------|-------------------------|--------------------|
| Inspection Date 01/03/2018 | Type Inspection Routine | Certificate Status Re-issued | Inspector 73 - James | County ALAMANCE |
|-------------------------------|----------------------------|---------------------------------|-------------------------|--------------------|

1

VIOLATIONS

| | |
|------------|--|
| 8.6.4.7 | Remove oil from the pit floor |
| 2.27.1.1.1 | Place the in-car Emergency Phone in working order. |

Items must be corrected by: 03/04/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Jeremy 3363806126

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ELON UNIVERSITY
CAMPUS BPX 84823
ELON, NC, 27244