



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18011-79-3177
State Number
13414

EQUIPMENT INSPECTED

State Number: 13414	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: ESCO	Speed: 120
Landings: 2	Installed: 08/24/1989	Rope Size: 0
Volts: 480	Complied: 03/23/2005	Entrances: 1
OWNER	OCCUPANT	
NORTHSIDE HIGH SCHOOL	NORTHSIDE HIGH SCHOOL	
7868 FREE UNION CHURCH ROAD	7868 FREE UNION CHURCH ROAD	
PINETOWN, NC, 27865	PINETOWN, NC, 27865	

INSPECTION INFORMATION

Inspection Date 01/11/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 79 - Cumberland	County BEAUFORT
-------------------------------	----------------------------	---------------------------------	------------------------------	--------------------

7

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: main office

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

NORTHSIDE HIGH SCHOOL
7868 FREE UNION CHURCH ROAD
PINETOWN, NC, 27865