N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18024-73-3214
State Number
H1241

EQUIPMENT INSPECTED

State Number: **H1241**
Capacity: 750
Landings: 3
Volts: 18

Type of Unit: Hand Lift
Manuf: GARAVENTA
Installed: 04/24/2002
Complied:

Floor to Floor: 1 to 3
Speed: 10
Rope Size:
Entrances: 2

OWNER
GROVE PARK BAPTIST CHURCH
108 TRAIL ONE
BURLINGTON, NC, 27215

OCCUPANT
GROVE PARK BAPTIST CHURCH
108 TRAIL ONE
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
01/24/2018	Routine	Re-issued	73 - James	ALAMANCE

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Mark Reich 3362272910 Inspector _____

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
GROVE PARK BAPTIST CHURCH
108 TRAIL ONE
BURLINGTON, NC, 27215