



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18024-73-4165
State Number
23100

EQUIPMENT INSPECTED

State Number: 23100	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 3	Installed: 06/06/2005	Rope Size:
Volts: 208	Complied: 06/06/2005	Entrances: 1

OWNER

JDK PROPERTY MANAGEMENT
202 S. FIFTH ST
MEBANE, NC, 27302

OCCUPANT

WINDMERE CONDOS #2
3010 WINSTON DRIVE
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 01/24/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6	place covers on ac/heat control wiring in machine room
8.6	Place covers on phone wiring in machine room
8.6	Clean pit
8.6	Place car lights in proper working order

Items must be corrected by: 03/25/2018

Elevator Name: JDK 919 636 3073

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: JDK Property Management 9196363073

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

JDK PROPERTY MANAGEMENT
202 S. FIFTH ST
MEBANE, NC, 27302