



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18024-73-418
State Number
24692

EQUIPMENT INSPECTED

State Number: 24692	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 3	Installed: 01/14/2009	Rope Size:
Volts: 208	Complied: 01/14/2010	Entrances: 1

OWNER
JDK PROPERTY MANAGEMENT
202 S FIFTH STREET
MEBANE, NC, 27302

OCCUPANT
WINDEREMERE CONDOMINIUMS
3010 WINSTON DR
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 01/24/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.4.7	Clean the pit and the pit equipment.
2.14.7.1.2	Place the passenger cab interior lights in working order. 50 lx or 5 fc @ the cab floor.
2.27.1.1.1	Place the in-car Emergency Phone in working order.
8.6	Place in case of fire sign onm each landing

Items must be corrected by: 03/25/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: JDK Property Management 9196363073

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

JDK PROPERTY MANAGEMENT
202 S FIFTH STREET
MEBANE, NC, 27302