



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18029-73-3767
State Number
19552

EQUIPMENT INSPECTED

State Number: 19552	Type of Unit: Passenger	Floor to Floor: L to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 3	Installed: 09/15/2000	Rope Size:
Volts: 200	Complied: 11/07/2000	Entrances: 1
OWNER	OCCUPANT	
TRINITY WORSHIP CENTER	TRINITY WORSHIP CENTER	
3157 S CHURCH ST	3157 S CHURCH ST	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 01/29/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.4.7	Clean the pit and the pit equipment.
2.27.1.1.1	Place the in-car Emergency Phone in working order.

Items must be corrected by: 03/30/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Cheryl O Brien 3365850605

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

TRINITY WORSHIP CENTER
3157 S CHURCH ST
BURLINGTON, NC, 27215