



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**18030-73-4424**  
State Number  
**12214**

EQUIPMENT INSPECTED

State Number: <b>12214</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 2	Installed: 08/20/1987	Rope Size:
Volts: 200	Complied: 08/20/1987	Entrances: 1
OWNER	OCCUPANT	
CHANDLER CONCRETE	CHANDLER CONCRETE	
PO BOX 131	1006 CHURCH ST	
BURLINGTON, NC, 27216-0131	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 01/30/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

2.7.3.4.1	Provide a self closing self-locking machine room / space door.
8.6.5.14.1	Provide the annual relief valve and hydraulic system pressure test.

Items must be corrected by: 03/31/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Jamie Nelms 3362261181

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CHANDLER CONCRETE  
PO BOX 131  
BURLINGTON, NC, 27216-0131