



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18031-73-0519
State Number
17863

EQUIPMENT INSPECTED

State Number: 17863	Type of Unit: Passenger	Floor to Floor: B to 2
Capacity: 4500	Manuf: THYSSEN KRUPP	Speed: 110
Landings: 4	Installed: 10/01/1998	Rope Size:
Volts: 200	Complied: 10/01/1998	Entrances: 2
OWNER	OCCUPANT	
DAVIS ST METHODIST CHURCH	DAVIS ST METHODIST CHURCH	
606 E DAVIS ST	606 E DAVIS ST	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 01/31/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.5.14.1	Provide the annual relief valve and hydraulic system pressure test.
8.6	Replace missing pickup roller on landing 1

Items must be corrected by: 04/01/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Arlene Domenico 3362264457

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

DAVIS ST METHODIST CHURCH
606 E DAVIS ST
BURLINGTON, NC, 27215