



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**18036-73-1459**  
State Number  
**24720**

EQUIPMENT INSPECTED

State Number: <b>24720</b>	Type of Unit: Passenger	Floor to Floor: 1 to 4
Capacity: 2500	Manuf: TKE	Speed: 350
Landings: 4	Installed: 09/23/2008	Rope Size: 3/4
Volts: 480	Complied: 09/23/2008	Entrances: 1
OWNER	OCCUPANT	
LABCORP	LABCORP HEADQUARTERS	
271 E FRONT ST	531 S SPRING STREET	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 02/05/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

2.2.5.1	Place the pit lights in working order. 100 lx or 10 fc @ the pit floor.
8.6.4.19.2 (b)	Provide the annual no load test.

Items must be corrected by: 04/06/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Lorrie Flinchum 3364367777

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

LABCORP  
271 E FRONT ST  
BURLINGTON, NC, 27215