N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18037-54-5279
State Number
4865

EQUIPMENT INSPECTED

State Number: **4865**
Capacity: 10000
Landings: 2
Volts: 560

Type of Unit: Freight
Manuf: OTIS
Installed: 04/16/1963
Complied: 04/19/1990

Floor to Floor: 1 to 2
Speed: 60
Rope Size:
Entrances: 2

OWNER
AVOCA INC
PO BOX 129
MERRY HILL, NC, 27957

OCCUPANT
AVOCA INC.
841 AVOCA FARM ROAD
MERRY HILL, NC, 27957

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
02/06/2018	Compliance	Issued	54 - Green	BERTIE

8

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: TOM RAY 252 482 2133 Inspector _____

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
AVOCA INC
PO BOX 129
MERRY HILL, NC, 27957