



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18043-73-541
State Number
25587

EQUIPMENT INSPECTED

State Number: 25587	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 4500	Manuf: TKE	Speed: 110
Landings: 2	Installed: 03/26/2008	Rope Size: 0
Volts: 480	Complied: 03/26/2008	Entrances: 2
OWNER	OCCUPANT	
CONE HEALTH	CONE HEALTH MEDICAL CENTER MEBANE	
HEALTH SERVICE DIVISION	3940 ARROW HEAD BVLD	
GREENSBORO, NC, 27401	MEBANE, NC, 27302	

INSPECTION INFORMATION

Inspection Date 02/12/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

5.1.21.1 Place the car alarm bell in working order. Minimum level of 80 dBA.

8.6.5.5.1 Where pressure piping, valves, and cylinders use packing glands or seals, they shall be examined and maintained to prevent excessive loss of fluid.

Items must be corrected by: 04/13/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Cherrie Speagle 3368323290

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CONE HEALTH
HEALTH SERVICE DIVISION
GREENSBORO, NC, 27401