



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18044-66-483
State Number
19883

EQUIPMENT INSPECTED

State Number: 19883	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 95
Landings: 2	Installed: 08/13/2001	Rope Size: 0
Volts: 208	Complied: 08/23/2001	Entrances: 1
OWNER	OCCUPANT	
ALEXANDER COUNTY SCHOOLS	ALEXANDER CENTRAL HIGH SCHOOL	
700 LILEDOWN ROAD	241 SCHOOL AVENUE	
TAYLORSVILLE, NC, 28681	TAYLORSVILLE, NC, 28681	

INSPECTION INFORMATION

Inspection Date 02/13/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 66 - Pacitti	County ALEXANDER
-------------------------------	----------------------------	---------------------------------	---------------------------	---------------------

2

VIOLATIONS

8.6.4.7 Remove oil from the pit floor also repack the leaking cylinder to fix problem
8.6.4.13.1 (c Place the door speeds in working order
8.6.4.13.1(i) Place the door restrictor in proper working order.
8.6.5.14.1 Provide the annual relief valve and hydraulic system pressure test.and I must witness testing this unit is shut off due to state violations
NOTE THIS UNIT IS IN BAD SHAPE THIS MUST BE WITNESSED TO ALL TESTING

Items must be corrected by: 02/13/2018

Elevator Name: # 2

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: hgi-stvl.gm@abcinns.com

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALEXANDER COUNTY SCHOOLS
700 LILEDOWN ROAD
TAYLORSVILLE, NC, 28681