



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18045-73-1655
State Number
15427

EQUIPMENT INSPECTED

State Number: 15427	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 2	Installed: 10/11/1994	Rope Size:
Volts: 208	Complied: 10/14/1994	Entrances: 1
OWNER		OCCUPANT
ALAMANCE - BURLINGTON SCHOOL SYSTEM		TURRENTINE MIDDLE SCHOOL
1712 VAUGHN RD		1710 EDGEWOOD AVE
BURLINGTON, NC, 27217		BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 02/14/2018	Type Inspection Compliance	Certificate Status Issued	Inspector 73 - James	County ALAMANCE
-------------------------------	-------------------------------	------------------------------	-------------------------	--------------------

1

VIOLATIONS

2.2.5.1 Place the pit lights in working order. 100 lx or 10 fc @ the pit floor.

Items must be corrected by: 04/15/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Frederick Sellars 3365706150

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE - BURLINGTON SCHOOL SYSTEM
1712 VAUGHN RD
BURLINGTON, NC, 27217