



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18045-73-4457
State Number
H823

EQUIPMENT INSPECTED

State Number: H823	Type of Unit: Hand Lift	Floor to Floor: LL to UL
Capacity: 550	Manuf: NATL W-O-V	Speed: 9
Landings: 2	Installed: 01/12/1998	Rope Size:
Volts: 110	Complied: 02/02/1998	Entrances: 2
OWNER		OCCUPANT
ALAMANCE - BURLINGTON SCHOOL SYSTEM		TURRENTINE MIDDLE SCHOOL
1227 VAUGHN RD		1710 EDGEWOOD AVE
BURLINGTON, NC, 27217		BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 02/14/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6 Place unit in working order or remove, 10 days to comply

Items must be corrected by: 02/24/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Frederick Sellars 3365706150

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE - BURLINGTON SCHOOL SYSTEM
1227 VAUGHN RD
BURLINGTON, NC, 27217