



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18046-73-4316
State Number
10162

EQUIPMENT INSPECTED

State Number: 10162	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: SOUTHERN	Speed: 75
Landings: 2	Installed: 12/08/1981	Rope Size:
Volts: 440	Complied: 12/08/1981	Entrances: 1
OWNER	OCCUPANT	
ED ALEXANDER FABRICS INC	ED ALEXANDER FABRICS INC	
ST RD 1184/INDUSTRY DR.	ST RD 1184/INDUSTRY DR.	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 02/15/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.4.7 Remove the water from the pit floor and take steps to prevent its re-entry.

Items must be corrected by: 04/16/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Tim Kaywell 5709512748

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ED ALEXANDER FABRICS INC
ST RD 1184/INDUSTRY DR.
BURLINGTON, NC, 27215