

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18051-73-5747 State Number 9192

		E	EQUIPMENT INSPECTED			
State Number: 9192		Type of Unit: Passenger			Floor to Floor: 1 to 2	
Capacity: 2000		Manuf: SOUTHERN		Speed: 125		
Landings: 2		Installed: 01/19/1979		Rope Size:		
Volts: 240		Complied: 02/09/1979		Entrances: 1		
OWNER		OCCUPANT				
PATE REAL ESTATE		LAB CORP "DUKE POWER BDLG"				
TOM PATE		508 LEXINGTON AVE				
BURLINGTON, NC, 27216		BURLINGTON, NC, 27215				
		INS	SPECTION INFORMATION			
Inspection Date 02/20/2018		Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
			VIOLATIONS			
8.6.5.14.1 3.6		annual relief valve and hydraulic s e of fire sign at each landing	system pressure test.			
Items must b	e corrected by: 03/	/22/2018				

TOM PATE

PATE REAL ESTATE

BURLINGTON, NC, 27216

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: