



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18052-66-1588
State Number
21973

EQUIPMENT INSPECTED

State Number: 21973	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 2	Installed: 06/08/2004	Rope Size: 0
Volts: 208	Complied: 07/01/2004	Entrances: 1
OWNER	OCCUPANT	
ANTIOCH BAPTIST CHURCH	ANTIOCH BAPTIST CHURCH	
580 ANTIOCH CHURCH ROAD	580 ANTIOCH CHURCH ROAD	
TAYLORSVILLE, NC, 28681	TAYLORSVILLE, NC, 28681	

INSPECTION INFORMATION

Inspection Date 02/21/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 66 - Pacitti	County ALEXANDER
-------------------------------	----------------------------	---------------------------------	---------------------------	---------------------

2

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: awpalmer@antioch580.org

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ANTIOCH BAPTIST CHURCH
580 ANTIOCH CHURCH ROAD
TAYLORSVILLE, NC, 28681