

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18052-66-3521 State Number H1334

2

	E	EQUIPMENT INSPECTED			
State Number: <b>H1334</b>	Type of Unit:	Hand Lift	Floor to Floor: 1 to 2		
Capacity: 750	Manuf: GARA	Manuf: GARAVENTA		Speed: 11	
Landings: 2	Installed: 01/2	Installed: 01/24/2003		Rope Size: 0	
Volts: 220	Complied: 01/	Complied: 01/24/2003		Entrances: 2	
OWNER		OCCUPANT			
ANTIOCH BAPTIST CHURCH		ANTIOCH BAPTIST CHURCH			
580 ANTIOCH CHURCH ROAL	D	580 ANTIOCH CHURCH ROAD			
TAYLORSVILLE, NC, 28681		TAYLORSVILLE, NC, 28681			
	INS	SPECTION INFORMATION			
Inspection Date 02/21/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 66 - Pacitti	County ALEXANDER	
		VIOLATIONS			
	ing on Corrected Violations Form	when the following corrections h	ave been made in order to b	oring your equipment into	
omplainace with current codes. iolations pointed out to: awpalm	er@antioch580.org		Inspector		
THIS IS NOT AN	Γo make changes to the invoice ma	= =			
	An invoice will be mailed to:	ANTIOCH BAPTIST CH 580 ANTIOCH CHURCH TAYLORSVILLE, NC. 2	I ROAD		