



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18060-73-3910
State Number
13709

EQUIPMENT INSPECTED

| | | |
|----------------------------|-------------------------|------------------------|
| State Number: 13709 | Type of Unit: Passenger | Floor to Floor: 1 to 3 |
| Capacity: 4000 | Manuf: THYSSEN KRUPP | Speed: 80 |
| Landings: 3 | Installed: 09/19/1991 | Rope Size: |
| Volts: 460 | Complied: 02/07/1994 | Entrances: 2 |
| OWNER | OCCUPANT | |
| LAB CORP | LAB CORP | |
| ATTN STEVE THACKER | 1447 YORK CT | |
| BURLINGTON, NC, 27215 | BURLINGTON, NC, 27215 | |

INSPECTION INFORMATION

| | | | | |
|-------------------------------|----------------------------|---------------------------------|-------------------------|--------------------|
| Inspection Date 03/01/2018 | Type Inspection Routine | Certificate Status Re-issued | Inspector 73 - James | County ALAMANCE |
|-------------------------------|----------------------------|---------------------------------|-------------------------|--------------------|

1

VIOLATIONS

- 8.6.5.5.1 Where pressure piping, valves, and cylinders use packing glands or seals, they shall be examined and maintained to prevent excessive loss of fluid.
- 8.6.4.7 Clean the pit and the pit equipment.

Items must be corrected by: 04/30/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Steve Thacker 3365167129

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

LAB CORP
ATTN STEVE THACKER
BURLINGTON, NC, 27215