

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18064-73-2717 State Number H1200

	F	EQUIPMENT INSPECTED			
State Number: H1200	Type of Unit: I	Hand Lift	Floor to Floor:	1 to 2	
Capacity: 750	Manuf: VPL GERAVEN		Speed: 11	Speed: 11	
Landings: 2	Installed: 10/26/2001		Rope Size:	Rope Size:	
Volts: 220	Complied: 10/26/2001		Entrances: 2		
OWNER		OCCUPANT			
ALAMANCE CO SCHOOLS		HOLT ELEM SCHOOL			
1712 VAUGHAN RD		4751 S HWY 62			
BURLINGTON, NC, 27217	BURLINGTON, NC, 27215				
	INS	SPECTION INFORMATION			
Inspection Date 03/05/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
		VIOLATIONS			
Items must be corrected by: 05. Notify the Elevator Bureau in writing complainace with current codes.		when the following corrections hav	e been made in order to br	ing your equipment int	
complainace with current codes. Violations pointed out to: Mariah	Vignali 3365706420		Inspector		
		ailing address please call: 919-733-			
THIS IS NOT AN	An invoice will be mailed to:	ALAMANCE CO SCHOOI 1712 VAUGHAN RD BURLINGTON, NC, 27217	LS		