

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18064-73-5888 State Number H1854

	E	EQUIPMENT INSPECTED			
State Number: <b>H1854</b>	Type of Unit: Hand Lift		Floor to Floor: 1	Floor to Floor: 1 to 2	
Capacity: 750 Manuf: ACCESS		Speed: 10			
Landings: 1	Installed: 05/17/2007		Rope Size: 0		
/olts: 220	Complied: 05/17/2007		Entrances: 2		
OWNER		OCCUPANT			
REFUGE TEMPLE CHURCH		REFUGE TEMPLE CHURCH			
152 N MAIN STREET	152 N MAIN STREE		ET		
BURLINGTON, NC, 27217		BURLINGTON, NC, 27217			
	INS	SPECTION INFORMATION			
Inspection Date 03/05/2018	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 73 - James	County ALAMANCE	
		VIOLATIONS			
otify the Elevator Bureau in writionplainace with current codes.	ng on Corrected Violations Form v	when the following corrections hav	ve been made in order to br	ing your equipment into	
Violations pointed out to: See comment		Inspector			
	Γo make changes to the invoice ma				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	REFUGE TEMPLE CHUR 152 N MAIN STREET BURLINGTON NC 27212			