

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18093-48-223 State Number 23469

			EQUIPMENT INSPECTED				
State Number: 23469 Type of Unit: Po			assenger	Floor to Flo	Floor to Floor: 1 to 3		
Capacity: 2000 Manuf: THYSS			SEN KRUPP	Speed: 55	Speed: 55		
Landings: 3 Installed: 09/08/20 Volts: 240 Complied: 09/09/2			3/2005	1			
			09/2005				
OWNER				OCCUPANT			
THE WOODLANDS @ CROW CREEK				CROW CREEK BLDG #6			
10255 BEACH DR SW				260 WOODLANDS WAY			
CALABASH, NC, 28467			CALABASH, NC, 28467				
			INSPECTION INFORMATION	N			
Inspection Date 04/03/2018		Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	10	
			VIOLATIONS				
8.6.5.5.2 8.6.4.8 8.6.4.7	Clean the m	Empty the drain bucket in the pit. Clean the machine room and the machine room equipment. Clean the pit and the pit equipment.					
2.7.9.1	Place the machine room or space lights in working order. 200 lx or 19 fc @ the machine room floor.						
8.6.4.19.2 (b)	Provide the annual no load test.						
8.0.4.19.2 (0)	I tovide the aimuai no todu test.						
Items must be	e corrected by:	05/03/2018					

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

complainace with current codes.

Violations pointed out to: UNAVAILABLE

THE WOODLANDS @ CROW CREEK

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into

An invoice will be mailed to: 10255 BEACH DR SW CALABASH, NC, 28467

Inspector __