NCDOL M. Department of John

Violations pointed out to: UNAVAILABLE

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18094-48-3265 State Number 23970

		EQUIPMENT INSPECTED		
State Number: 23970 Type of Unit: Passenger		assenger	Floor to Floor: 1 to 3	
Capacity: 2000	Manuf: THYSSEN KRUPP		Speed: 55	
Landings: 3	Installed: 03/29/2006 Complied:		Rope Size: 0 Entrances: 1 OCCUPANT	
Volts: 230				
OWNER				
THE WOODLANDS @ CROW CREEK			CROW CREEK CONDO #8	
10255 BEACH DR SW		240 WOODLANDS WAY		
CALABASH, NC, 28497			CALABASH, NC, 28467	
		NSPECTION INFORMATIO	N	
Inspection Date 04/04/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
		VIOLATIONS		
8.6.4.7	Clean the pit and the pit equipment.			
5.1.21.1	Place the car alarm bell in working order. Minimum level of 80 dBA.			
2.27.1.1.1	Place the in-car Emergency Phone in working order.			
8.6.4.19.2 (b)	.2 (b) Provide the annual no load test.			
Items must be correct	ed by: 05/04/2018			
Notify the Elevator Burea omplainace with current	u in writing on Corrected Violations Form	n when the following correction	ons have been made in order to	bring your equipment into

10255 BEACH DR SW

CALABASH, NC, 28497

THE WOODLANDS @ CROW CREEK

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

Inspector ___