



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18095-80-5574
State Number
8543

EQUIPMENT INSPECTED

State Number: 8543	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 12000	Manuf: SOUTHERN	Speed: 100
Landings: 2	Installed: 02/03/1976	Rope Size:
Volts: 480	Complied: 02/14/2000	Entrances: 1
OWNER	OCCUPANT	
PERDUE INC.	PERDUE FARMS INC	
PO BOX 1537	HWY 308 WEST	
SALISBURY, MD, 21802	LEWISTON, NC, 27849	

INSPECTION INFORMATION

Inspection Date 04/05/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 80 - Jenkins	County BERTIE
-------------------------------	----------------------------	---------------------------------	---------------------------	------------------

8

VIOLATIONS

2.2.5.1	Place the pit lights in working order. 100 lx or 10 fc @ the pit floor.
2.15.2.2	Replace the worn / damaged car slide guides.
2.11.11.5	Replace the damaged hoistway doors. Bottom section 1st and 2nd floor
A17.2	Piston needs replacing
A17.2	Repair conduct in pit

Items must be corrected by: 07/04/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: MIKE HARDY

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

PERDUE INC.
PO BOX 1537
SALISBURY, MD, 21802