

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18096-48-5193 State Number 24567

| | | EQUIPMENT INSPECTED | | | |
|--------------------------------|--|---------------------------------|----------------------------|---------------------------|--|
| State Number: 24567 | | Type of Unit: Passenger | | Floor to Floor: 1 to 3 | |
| Capacity: 2000 | Manuf: THYSS | | Speed: 55 | 0 | |
| Landings: 3 Volts: 230 | Installed: 03/07 Complied: | //2007 | Rope Size: Entrances: | | |
| OWNER | Compiled. | OCCUID | OCCUPANT | | |
| THE WOODLANDS | a CROW CREEK | | AN1 CREEK - BLDG #15 | | |
| 10255 BEACH DR SV | | | TH CROW CREEK DR | | |
| CALABASH, NC, 284 | | | ASH, NC, 28467 | | |
| |] | INSPECTION INFORMATION | | | |
| Inspection Date 04/06/2018 | Routine | Certificate Status Re-issued | Inspector 48 - Martin | County BRUNSWICK | |
| | | VIOLATIONS | | | |
| 2.27.1.1.1 | Place the in-car Emergency Phone in wor | king order. | | | |
| 2.27.1.1.1 8.6.4.8 | Place the in-car Emergency Phone in wor Clean the machine room and the machine | king order. | | | |
| | Clean the machine room and the machine | king order. | | | |
| 8.6.4.8 Items must be correct | Clean the machine room and the machine ted by: 05/06/2018 au in writing on Corrected Violations For | king order. room equipment. | have been made in order to | bring your equipment into | |

CALABASH, NC, 28467

THE WOODLANDS @ CROW CREEK 10255 BEACH DR SW