



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18099-79-0313
State Number
14964

EQUIPMENT INSPECTED

State Number: 14964	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: US ELEVATOR	Speed: 100
Landings: 2	Installed: 04/02/1993	Rope Size: 0
Volts: 480	Complied: 04/02/1993	Entrances: 1

OWNER

BEAUFORT COUNTY COMM COLLEGE
5337 US HWY 264 EAST
WASHINGTON, NC, 27889

OCCUPANT

BEAUFORT COMMUNITY COLLEGE
5337 HWY 264 EAST
WASHINGTON, NC, 27889

INSPECTION INFORMATION

Inspection Date 04/09/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 79 - Cumberland	County BEAUFORT
-------------------------------	----------------------------	---------------------------------	------------------------------	--------------------

7

VIOLATIONS

Elevator Name: #1 Bldg

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: maint office

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BEAUFORT COUNTY COMM COLLEGE
5337 US HWY 264 EAST
WASHINGTON, NC, 27889