



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18106-73-1157
State Number
10994

EQUIPMENT INSPECTED

State Number: 10994	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 2	Installed: 02/14/1986	Rope Size:
Volts: 460	Complied: 02/14/1986	Entrances: 1
OWNER	OCCUPANT	
BURLINGTON POLICE BLDG	BURLINGTON POLICE BLDG	
PO BOX 1358	267 W FRONT ST	
BURLINGTON, NC, 27216	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 04/16/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6 Place in case of fire sign at each landing

Items must be corrected by: 06/15/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Chris Verdeck 3365162424

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BURLINGTON POLICE BLDG
PO BOX 1358
BURLINGTON, NC, 27216