NCDOL NCDOL N. Department of labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18113-48-3182
State Number 22560

		EQUIPMENT INSPECTED			
State Number: 22560 Capacity: 300 Landings: 4 Volts: 208	Manuf: THYSS Installed: 11/18	Type of Unit: Passenger Manuf: THYSSEN KRUPP Installed: 11/18/2004 Complied: 11/18/2004		Floor to Floor: 1 to 4 Speed: 125 Rope Size: Entrances: 1	
			Endances. 1		
OWNER	OCCUPANT ISLANDER RESORT - BLDG. #54 4 VIA DOLOROSA				
CAM					
P.O. BOX 8126 OCEAN ISLE BEACH, NC, 2	28469	OCEAN ISLE BEACH, NC, 28469			
		INSPECTION INFORMATION			
Inspection Date 04/23/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
8.6.4.19.2 (b) P.	rovide the annual no load test.				
Items must be corrected by:	05/23/2018				
Notify the Elevator Bureau in w complainace with current codes.	riting on Corrected Violations For	m when the following corrections	have been made in order to	bring your equipment into	
Violations pointed out to: UNA	VAILABLE				
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	CAM P.O. BOX 8126 OCEAN ISLE BEACH,	NC, 28469		