## NCDOL NCDOL NA Department of labor

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18113-48-4558
State Number 23583

10

	]	EQUIPMENT INSPECTED			
State Number: 23583 Capacity: 3000 Landings: 4 Volts: 208 OWNER CAM	Manuf: THYSSE Installed: 01/10/2	Type of Unit: Passenger  Manuf: THYSSEN KRUPP Installed: 01/10/2006 Complied: 01/10/2006  OCCUPANT ISLANDER RESOL			
P.O. BOX 8126 OCEAN ISLE BEACH, NC, 28469		157 VIA OLD SOUND BLVD OCEAN ISLE BEACH, NC, 28469			
	IN	SPECTION INFORMATION			
Inspection Date 04/23/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
8.6.4.13.1 ( c Place the	e door re-opening device in proper v	vorking order. [DOOR OPEN B	SUTTON		
8.6.4.7 Clean the 8.6.4.19.2 (b) Provide to	e door re-opening device in proper very the pit and the pit equipment.  The annual no load test.  DE MISSING CAUTION SIGNS OF		UTTONJ		
8.6.4.7 Clean the 8.6.4.19.2 (b) Provide to	e pit and the pit equipment. the annual no load test. DE MISSING CAUTION SIGNS O		UTTONJ		
8.6.4.7 Clean the 8.6.4.19.2 (b) Provide to 6.1.6 PROVIDE	e pit and the pit equipment. the annual no load test. DE MISSING CAUTION SIGNS O	N 2ND AND 3RD FL		bring your equipment into	

CAM P.O. BOX 8126

OCEAN ISLE BEACH, NC, 28469