



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18128-73-1275
State Number
5904

EQUIPMENT INSPECTED

State Number: 5904	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 3000	Manuf: WESTBROOK	Speed: 35
Landings: 2	Installed: 08/09/1967	Rope Size:
Volts: 550	Complied: 09/19/1994	Entrances: 1
OWNER	OCCUPANT	
KINGSDOWN INC	KINGSDOWN INC	
126 W HOLT ST	126 W HOLT ST	
MEBANE, NC, 27302	MEBANE, NC, 27302	

INSPECTION INFORMATION

Inspection Date 05/08/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

- 2.14.4.7 Repair the damaged car gate.
- 8.6.4.8.2 Articles or materials not necessary for the maintenance or operation of the elevator shall not be stored in machinery spaces, machine rooms, control spaces and control rooms.

Items must be corrected by: 07/07/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Rick Allmond 3362666979

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

KINGSDOWN INC
126 W HOLT ST
MEBANE, NC, 27302