

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18129-73-153
State Number 31096

	I	EQUIPMENT INSPECTED			
State Number: 31096	Type of Unit: Passenger		Floor to Floor: 1	Floor to Floor: 1 to 2	
Capacity: 4500	Manuf: OTIS		Speed: 100		
Landings: 2	Installed: 06/22/2017		Rope Size:		
Volts: 208	Complied:		Entrances: 1		
OWNER	OCCUP.	ANT			
THE LAMBS CHAPEL	THE LA	THE LAMBS CHAPEL AIRPORT CAMPUS			
415 ROXBORO ROAD	ALAMA	ALAMANCE ROAD			
HAW RIVER, NC, 27258	BURLIN	BURLINGTON, NC, 27215			
	IN	SPECTION INFORMATION			
Inspection Date 05/09/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
		VIOLATIONS			

THE LAMBS CHAPEL

415 ROXBORO ROAD HAW RIVER, NC, 27258