

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18129-73-1739
State Number 25399

1

		EQUIPMENT INSPECTED		
State Number: 25399 Type of Unit: I			Floor to Floor: 1 to 3	
Capacity: 2500 Manuf: SCAND			Speed: 100	
Landings: 3 Installed: 10/26/		26/2007	Rope Size:	
Volts: 208 Complied:			Entrances: 1	
OWNER		OCCUPANT		
ETHAN POINTE APARTMENTS		ETHAN POINTE AOARTMENTS		
2978 ETHAN POINTE		1176 KIRKPATRICK ROAD BURLINGTON, NC, 27215		
BURLINGTON, NC, 2	7213	BURLINGTON, NC		
	Π	NSPECTION INFORMATION		
Inspection Date 05/09/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
		VIOLATIONS		
8.6.4.13.1 (k) spaces and Take steps	materials not necessary for the mainternaction control rooms. to make the hoistway doors self-closing a n-car Emergency Phone in working order.	nd self-locking.	tot be stored in machinery	spaces, machine rooms, co
complainace with curren	au in writing on Corrected Violations Forn	n when the following corrections hav	ve been made in order to br Inspector	
THIS IS NOT AN		nailing address please call: 919-733- ETHAN POINTE APARTM		

2978 ETHAN POINTE DRIVE BURLINGTON, NC, 27215