

Violations pointed out to: Karen Bacon 3365843337

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18129-73-457 State Number 25342

		E	EQUIPMENT INSPECTED			
State Number: 25342		Type of Unit: Passenger		Floor to Floor: 1 to 3		
Capacity: 2500		Manuf: SCHIN	Manuf: SCHINDLER		Speed: 100	
Landings: 3		Installed: 10/24	Installed: 10/24/2007		Rope Size:	
Volts: 208		Complied:	Complied:		Entrances: 1	
OWNER			OCCUPANT			
ETHAN POINTE APARTMENTS		S	ETHAN POINTE APARTMENTS			
2978 ETHAN POINTE DRIVE			1176 KIRKPATRICK ROAD			
BURLINGTON, NC, 27215			BURLINGTON, NC, 27215			
		INS	SPECTION INFORMATION			
Inspection Date 05/09/2018		Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
			VIOLATIONS			
8.6.1.6.5 8.6.4.7 8.6.4.13.1(i) 8.6	Clean the pit a	as ABC fire extinguisher in the made and the pit equipment. It restrictor in proper working order unit in proper working order		expired		
Items must b	e corrected by: 07	/08/2018				
	or Bureau in writi	ng on Corrected Violations Form v	when the following corrections have	re been made in order to bri	ng your equipment in	

Page 1 of 1

ETHAN POINTE APARTMENTS

2978 ETHAN POINTE DRIVE

BURLINGTON, NC, 27215

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

Inspector ___