



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18143-48-1215
State Number
11693

EQUIPMENT INSPECTED

State Number: 11693	Type of Unit: Passenger	Floor to Floor: G to 3
Capacity: 2000	Manuf: KONE	Speed: 125
Landings: 4	Installed: 02/19/1987	Rope Size: .
Volts: 0	Complied: 02/19/1987	Entrances: 4
OWNER	OCCUPANT	
WEST BEACH VILLA	WEST BEACH VILLA	
2714 W BEACH DRIVE	2714 W. BEACH DRIVE	
LONG BEACH, NC, 28461	LONG BEACH, NC, 28461	

INSPECTION INFORMATION

Inspection Date 05/23/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

8.6.4.7	Clean the pit and the pit equipment.
8.6.4.19.2 (b)	Provide the annual no load test.
N/A	CLEAN RUST OFF OF CAR TOP

Items must be corrected by: 06/22/2018

Elevator Name: # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: MGMT.

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
WEST BEACH VILLA
2714 W BEACH DRIVE
LONG BEACH, NC, 28461