



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18143-73-0235
State Number
13815

EQUIPMENT INSPECTED

State Number: 13815	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 125
Landings: 2	Installed: 10/25/1990	Rope Size:
Volts: 208	Complied: 10/25/1990	Entrances: 1
OWNER	OCCUPANT	
ALAMANCE CO SCHOOLS	GRAHAM MIDDLE SCHOOL	
1712 VAUGHAN RD	311 PINE STREET	
BURLINGTON, NC, 27217	GRAHAM, NC, 27253	

INSPECTION INFORMATION

Inspection Date 05/23/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.4.7 Remove the water from the pit floor and take steps to prevent its re-entry.

Items must be corrected by: 07/22/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Angelica Solomon 3365706460

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE CO SCHOOLS
1712 VAUGHAN RD
BURLINGTON, NC, 27217