



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**18143-73-0533**  
State Number  
**H1854**

EQUIPMENT INSPECTED

State Number: <b>H1854</b>	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: ACCESS	Speed: 10
Landings: 1	Installed: 05/17/2007	Rope Size: 0
Volts: 220	Complied: 05/17/2007	Entrances: 2
OWNER	OCCUPANT	
REFUGE TEMPLE CHURCH	REFUGE TEMPLE CHURCH	
152 N MAIN STREET	152 N MAIN STREET	
BURLINGTON, NC, 27217	BURLINGTON, NC, 27217	

INSPECTION INFORMATION

Inspection Date 05/23/2018	Type Inspection Condemned	Certificate Status Not Issued	Inspector 73 - James	County ALAMANCE
-------------------------------	------------------------------	----------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6 No contact was made from owner, Attempted to inspect on 3-5-18, left notice on door. Unit condemned

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Notice left on door

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

REFUGE TEMPLE CHURCH  
152 N MAIN STREET  
BURLINGTON, NC, 27217