



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18143-73-2929
State Number
19587

EQUIPMENT INSPECTED

State Number: 19587	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 95
Landings: 2	Installed: 01/22/2001	Rope Size:
Volts: 208	Complied: 01/31/2001	Entrances: 1
OWNER	OCCUPANT	
COMMUNITY ONE	COMMUNITY ONE	
1128 S MAIN ST	1128 S MAIN ST	
GRAHAM, NC, 27253	GRAHAM, NC, 27253	

INSPECTION INFORMATION

Inspection Date 05/23/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.4.7	Remove the water from the pit floor and take steps to prevent its re-entry.
2.2.2.6	Provide a sump pump cover, the cover shall be secure and level with the floor.
2.2.2.4	Place the sump pump in working order.
8.6.4.13.1(i)	Place the door restrictor in proper working order.

Items must be corrected by: 07/22/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Karen Reimiller 3362261223

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

COMMUNITY ONE
1128 S MAIN ST
GRAHAM, NC, 27253