

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18151-73-0258
State Number 11639

EQUIPMENT INSPECTED						
State Number: 11639		Type of Unit: Pas	Type of Unit: Passenger		Floor to Floor: 1 to 3	
Capacity: 2500 Manuf		Manuf: THYSSE	anuf: THYSSEN KRUPP		Speed: 125	
Landings: 3 Installed: 03		Installed: 03/06/1	986	Rope Size:	Rope Size:	
Volts: 200 Complied:		Complied: 03/06/	1986	Entrances: 1	Entrances: 1	
OWNER			OCCUPANT			
CAROLINA BIOLOGICAL SUPPLY		PPLY	CAROLINA BIOLOGICAL SUPP.			
ATTN ACCOUNTS PAYABLE			1308 RAINEY ST			
BURLINGTON, NC, 27216-6005		5	BURLINGTON, NC, 27215			
		IN:	SPECTION INFORMATION			
Inspection Date 05/31/2018		Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
			VIOLATIONS			
otify the Eleva	be corrected by: 07 tor Bureau in writi h current codes.		when the following corrections hav	re been made in order to br	ing your equipment into	
_		Valker 3365386205		Inspector		

CAROLINA BIOLOGICAL SUPPLY

ATTN ACCOUNTS PAYABLE BURLINGTON, NC, 27216-6005

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: