



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18151-73-3770
State Number
4698

EQUIPMENT INSPECTED

State Number: 4698	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 7500	Manuf: SOUTHERN	Speed: 60
Landings: 2	Installed: 10/01/1962	Rope Size: 0
Volts: 550	Complied: 04/08/2004	Entrances: 1
OWNER	OCCUPANT	
CAROLINA FINISHING OF NC	CAROLINA FINISHING OF NC LLC	
PO BOX 2226	220 ELMIRA ST	
BURLINGTON, NC, 27216	BURLINGTON, NC, 27217	

INSPECTION INFORMATION

Inspection Date 05/31/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.4.7	Clean the pit and the pit equipment.
2.2.5.1	Place the pit lights in working order. 100 lx or 10 fc @ the pit floor.

Items must be corrected by: 07/30/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Jim Kvarnstrom 4139490229

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CAROLINA FINISHING OF NC
PO BOX 2226
BURLINGTON, NC, 27216