



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**18156-73-1010**  
State Number  
**H1137**

EQUIPMENT INSPECTED

State Number: <b>H1137</b>	Type of Unit: Hand Lift	Floor to Floor: LL to UL
Capacity: 750	Manuf: GARAVENTA	Speed: 10
Landings: 2	Installed: 05/29/2001	Rope Size:
Volts: 220	Complied: 05/29/2001	Entrances: 2
OWNER	OCCUPANT	
ALAMANCE BURLINGTON SCHOOLS	WILLIAMS HIGH SCHOOL	
1712 VAUGHN RD	1307 S CHURCH ST	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 06/05/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Robert Drummond 3365706161

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE BURLINGTON SCHOOLS  
1712 VAUGHN RD  
BURLINGTON, NC, 27215