NCDOL NCDOL NA Department of John

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 18158-48-0069 State Number H1512

	E	EQUIPMENT INSPECTED		
state Number: H1512 Type of Unit: Hand Lift		Hand Lift	Floor to Floor: 1 to 2	
Capacity: 750	Manuf: ACCE	Manuf: ACCESS		
Landings: 2	Installed: 08/17/2004		Rope Size:	
Volts: 110 Complied: 08/1		17/2004 Entrances: 2		
OWNER OCCUPANT				
SHALLOTTE 1ST BAP CHURCE	SHALLOTTE 1ST BAP CHURCH			
4486 MAIN STREET		4486 MAIN STREET SHALLOTTE, NC, 28459		
SHALLOTTE, NC, 28459				
	INS	SPECTION INFORMATION		
Inspection Date 06/07/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK 1
		VIOLATIONS		
Elevator Name: # 1				
Notify the Elevator Bureau in writing complainace with current codes.	g on Corrected Violations Form v	when the following corrections	have been made in order to	bring your equipment into
Violations pointed out to: Mgmt.			Inspector	
To	o make changes to the invoice ma			
THIS IS NOT AN	n invoice will be mailed to:	SHALLOTTE 1ST BAP 4486 MAIN STREET SHALLOTTE, NC, 284:	CHURCH	