



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18166-79-4191
State Number
N7.5

EQUIPMENT INSPECTED

State Number: N7.5	Type of Unit: Freight	Floor to Floor: 1 to 4
Capacity: 2000	Manuf: OTIS	Speed: 100
Landings: 4	Installed: 06/05/1975	Rope Size: 1/2
Volts: 220	Complied: 06/05/1975	Entrances: 2
OWNER	OCCUPANT	
MRS BLACKSTONE	THE RICH COMPANY	
C/O PAMLICO PROPERTIES	147 W MAIN ST	
WASHINGTON, NC, 27889	WASHINGTON, NC, 27889	

INSPECTION INFORMATION

Inspection Date 06/15/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 79 - Cumberland	County BEAUFORT
-------------------------------	----------------------------	---------------------------------	------------------------------	--------------------

7

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: main office

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

MRS BLACKSTONE
C/O PAMLICO PROPERTIES
WASHINGTON, NC, 27889