



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
18170-73-1639
State Number
29228

EQUIPMENT INSPECTED

State Number: 29228	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 3000	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 06/24/2014	Rope Size:
Volts: 480	Complied: 06/24/2014	Entrances: 1
OWNER	OCCUPANT	
CLOVER GARDEN SCHOOL	CLOVER GARDEN SCHOOL	
2454 ALTMAHAW UNION ROAD	2454 ALTMAHAW UNION ROAD	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 06/19/2018	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Brandi Simmons 3365247659

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CLOVER GARDEN SCHOOL
2454 ALTMAHAW UNION ROAD
BURLINGTON, NC, 27215